THE TWELFTH FRET INSTRUMENT SPEC SHEET



Employee	GM Date 15 feb 2018							
Instrument Information & Specs								
Type of Instrument	Acoustic Guitar Year 1942 Weight (lbs) 4.05 lb							
Brand	Martin Model 000-45 Left Handed Right Handed							
Serial No.	80751 Colour natural Tuners Waverly							
Nut	Synthetic Nut [1-11/16" (43mm) Inlay Pearl Width							
Neck Joint	Dovetail Neck Mahogany							
Fretboard	Ebony Neck Profile Medium V							
Neck Radius	Other Scale 24.75" (628mm) 12" radius; previous refret Length							
Body	Spruce Top, Rosewood back/sides Bridge Type Acoustic (standard)							
Saddle	Bone Hardware/ Gold Made in USA Plating							
Electronics	● Hard Case Type of case/bag							
	O Gig Bag Comes with original case plus black Calton flight case							
CITES	RequiredNot Required							

Condition of Instrument

Action	Good	○ Fair	O Poor		Notes	4/64 treble, 6/64 bass; at "low fingerstyle action"	
Frets	Good	○ Fair	O Poor		Notes	newly refretted in our workshop.	
Neck Angle	Good	○ Fair	O Poor		Notes		
Nut Slots	Good	○ Fair	O Poor		Notes	Standard 1960s Martin factory synthetic nut.	
Truss Rod	Good	○ Fair	O Poor		Notes	Fixed truss rod: neck bow is correct as it should be.	
Tuners	Good	○ Fair	O Poor		Notes	New Waverly tuners. The best there are !!	
Fretboard	Good	○ Fair	O Poor		Notes	minor fretboard and inlay wear and tear from 76 years playing	
Aesthetic/ Finish	Good	○ Fair	O Poor		Notes	Exceptionally clean example	
Saddle(s)	Good	○ Fair	O Poor		Notes	4/64 saddle exposed. action is as low as anybody would want	
Bridge/ Tailpiece	Good	○ Fair	O Poor		Notes		
Electronics	○ Good	○ Fair	O Poor	● N/A	Notes		
Case/Gig Bag	Good	○ Fair	O Poor	O N/A	Notes	includeds original vintage and Calton case	
Repair	The best example 000-45 I have seen in years. Plays very nicely and the tone is full and						

Repair History / Additional Comments The best example 000-45 I have seen in years. Plays very nicely and the tone is full and sweet. Very nice when we see an exceptional vintage guitar that also sounds as good as it looks!! The finish is equally old and displays typical factory lacquer checking. Our feeling is that Martin probably re-sprayed the treble side and possibly the back in the 1950s but Martin has no record and the owner only a vague memory that it was sent to the Martin Factory 60 or 70 odd years ago for some work. Grant MacNeill